

# Ribbon > Home tab > Viewport group > Toggle barcode


## Button identification




## Associated command

## Function description

When enabled, the viewport looks like this:



When disabled, the widget is hidden from view:



## Related functionality

[Ribbon > Home tab](#)

From: <https://docs.pathomation.com/pimsls/3.1.0/> - PIMS LS 3.1.0

Permanent link: [https://docs.pathomation.com/pimsls/3.1.0/doku.php?id=ribbon\\_home\\_viewport\\_toggle\\_barcode&rev=1676035645](https://docs.pathomation.com/pimsls/3.1.0/doku.php?id=ribbon_home_viewport_toggle_barcode&rev=1676035645)

Last update: 2023/02/10 16:27

